## Maryland Historical Trust State Historic Sites Inventory Form

Magi No. 0208465404

Survey No. AA-846

DOE yes no Demolished New house built 1996 on site

1. Nar	ne (indica	te preferred name)	•	
historic	VELMEADE I			
and/or commo	n			
2. Loc	ation			
street & numb	er Patuxent	River Road		not for publication
city, town	Davidsonv	ville vicinity of	4th congressional district	
state	Maryland	county	y Anne Arundel Cou	nty
3. Cla	ssificatio	n		
Category  district building(s _X_ structure site object	Ownership public s) _X_ private both Public Acquisit in process being consid not_applic	yes: restricted lered yes: unrestricted	entertainment government	museum park private residence religious scientific transportation X other: ruin
<u>4. Ow</u>	ner of Pro	perty (give names	and mailing address	es of <u>all</u> owners)
name	John Haas			
street & number	er 9336 Worrel	1 Avenue	telephone r	no.:
city, town	Lanham	stat	ce and zip code MD	20706
5. Loc	ation of I	Legal Descript	ion	
courthouse, re	gistry of deeds, etc.	Anne Arundel County (	Courthouse	liber 0834
street & number	er	South Street		folio 470
city, town		Annapolis	state	MD
6. Rep	presentati	ion in Existing	Historical Surv	veys
title				
date	survey records		federal sta	ite <u>county</u> local
city, town			state	

## 7. Description

Survey No. AA-846

Condition     Check one     Check one       excellent     deteriorated     unaltered     x original site       good     x ruins     altered     moved     moved       fair     unexposed	excellent deteriorated good _X_ ruins	unaltered	X original site	
--	---------------------------------------	-----------	-----------------	--

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The house is located approximately one quarter mile to the east of Patuxent River Road and approximately one-half mile north of Maryland Route 214. The house faces west and is situated on a small knoll.

The house is a decaying ruin. The roof is virtually gone, exposing the interior to the elements. Most of the weatherboard siding is still intact. However, the siding on the southwest corner is gone, exposing heavy timber construction with a diagonal brace.

The house is a two-story, three-bay, side passage floor plan. The west or front elevation has 9/6 windows on the first story and 6/6 windows on the second story with remnants of shutters. The entrance once had a gable roof porch. The outline of the gable remains.

On the north elevation of the house, two chimneys flank a door opening covered by a shed type structure. The west chimney was once partially enclosed by a story-and-one-half structure. A fireplace is at grade level, its opening supported by an iron lintel. There is a flue opening on each level. The one-half story level of the chimney still exhibits remains of plaster which had been applied to the brick. The chimney has asymmetrical shoulders. The ghost of the gable roof line terminates with a flair at the bottom and has been patched with weatherboard. The chimney to the east shoulders in at the second floor level. Both chimney tops have crumbled to below the roof line.

The east or rear facade of the house has three bays with 6/6 windows; the bay to the south is a door.

The south elevation has two bays with 9/6 windows.

The foundation is brick laid in random bond with notched sills.

All interior description is from observations made from the exterior. Due to the advanced state of decay and the request of the owner, the structure was not entered. Information was gathered through windows and other openings.

The stair rises against the south wall of the entrance hall. The landing turns to the left and reverses direction. The turned walnut newel post and part of the balustrade survive, but the handrail has collapsed. The doors and windows have simple mouldings.

In the parlor are exposed riven laths. The flooring is tongue-and-groove random-width pine. The doors are paneled 6/2 with box locks and white porcelain knobs.

There are paneled 6/2 paired doors between the double parlors. The mantel consists of board surrounds with simple columns (with subtle entasis) flanking the opening and large scrolled brackets flanking a convex frieze below a complex mold shelf with Greek Revival details.

<u> </u>	1911110ance		Survey No. AA-0	+0
Period prehicular preh	-1499 _X_ archeology-historic -1599 agriculture -1699 _X_ architecture -1799 art -1899 commerce		law     literature     military     music     philosophy     politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	dates	Builder/Architect		
check:	Applicable Criteria:A and/or Applicable Exception:A		EFG	
	Level of Significance:	nationalstate _	_local	
Prepare support.	both a summary paragraph o	of significance and a	a general statement o	f history and

8. Significance

The house known as Velmeade I is now in ruins and allows only limited analysis. The house was a two-and-one-half story, three bay dwelling with a side passage, double parlor plan. The original gable roof has collapsed, but the frame walls and paired brick chimneys survive up to the old eave line. Of particular interest is the outline of an original wing on the north gable end and the original chimney with iron lintel that once served the wing.

## 9. Major Bibliographical References

10. Geographical Data	
Acreage of nominated property  Quadrangle name  UTM References do NOT complete UTM references	Quadrangle scale
Zone Easting Northing	Zone Easting Northing
C	P
Verbal boundary description and justification	
List all states and counties for properties overlapping	state or county boundaries
state code cou	nty code
state code cou	nty code
11. Form Prepared By	
name/title Davidsonville Survey Group	
organization Davidsonville Area Civic Association	date 2/84
street & number 1521 Themes Drive	telephone 798-6145
city or town Davidsonville	state MD 21035

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401


(301) 269-2438


## #7. Continuation sheet, page 2

The remaining doors on the second floor have six panels with box locks and white porcelain knobs. All other doors have raised panels.


The second floor has collapsed. There is no cellar.

Remains of several outbuildings are scattered to the south and west of the house. Dense undergrowth did not allow for measurement or detailed description. What may have been a barn is to the southwest and a carriage house or garage may have been to the south. According to the present owners, two wells to the east have been filled in with dirt, rubble and concrete. These were not observed.





AA-846 Velmeade I, site (demolished c. 1996) Bowie Quadrangle






PLATE II-8: Site AA846 Facing East




PLATE II-9: Site AA846 Facing North Northeast



PLATE II-6: Site AA846 Facing Southwest



PLATE II-7: Site AA846 Facing Northeast



PLATE II-5: Corn Crib, Site AA846











